

# **BECO**

WIRE HARNESS

# EV

# WIRING

# SOLUTIONS



## **Common Failures**

- ✓ Overheating under high current loads
- ✓ EMI interference causing signal loss
- ✓ Connector loosening due to vibration
- ✓ Insulation damage in compact layouts

## **BECO Solutions**

- ✓ High-current, heat-resistant harness assemblies
- ✓ EMI-shielded cables for signal stability
- ✓ Vibration-resistant connectors
- ✓ Custom designs for batteries, motors, and power electronics